

# Fluke 971 Temperature Humidity Meter

## Product Images

---



## Description

---

The Fluke 971 Temperature Humidity Meter is the perfect tool for monitoring air quality. With a rugged holster and protected sensor, the lightweight Temperature Humidity Sensor is built to last and perform

- Backlit dual display of humidity / temperature.
- Temp. range from  $-20^{\circ}\text{C}$  to  $60^{\circ}\text{C}$  ( $-4^{\circ}\text{F}$  to  $140^{\circ}\text{F}$ ).
- Relative humidity from 5 % to 95 %.
- Dew point and wet bulb temperatures.
- 99 record storage capacity.
- Ergonomic belt clip and protective holster.
- Compact and lightweight.
- Min/Max/Avg Data hold.
- Low battery indicator.
- Note: This item is POA (Price on Application). Please contact our customer care division for more information