

Fluke 971 Temperature Humidity Meter

Product Images



Description



The Fluke 971 Temperature Humidity Meter is the perfect tool for monitoring air quality. With a rugged holster and protected sensor, the lightweight Temperature Humidity Sensor is built to last and perform

- Backlit dual display of humidity / temperature.
- Temp. range from -20°C to 60°C (-4°F to 140°F).
- Relative humidity from 5 % to 95 %.
- Dew point and wet bulb temperatures.
- 99 record storage capacity.
- Ergonomic belt clip and protective holster.
- Compact and lightweight.
- Min/Max/Avg Data hold.
- Low battery indicator.
- Note: This item is POA (Price on Application). Please contact our customer care division for more information