

# Fluke 376 FC True-RMS Clamp Meter

## Product Images

---



## Description

---



The Fluke 376 FC True-RMS Clamp Meter with iFlex is an advanced troubleshooting tool, perfect for both industrial and commercial electricians. The True-RMS Clamp Meter allows the user to log, trend and monitor measurements whilst keeping away from the arc flash zone

- Uses an integrated low-pass filter for accurate measurements of non-linear signals (adjustable speed drives, electronic ballasts and other non-linear loads)
- Voltage to 1000 V AC or DC
- Resistance to 60k $\Omega$  with continuity detection
- 500 mV DC measurement range to interface with other accessories
- 1000  $\mu$ F capacitance measurement
- Contains 376 FC True-RMS Clamp Meter, 18-inch iFlex Flexible Current Probe, TPAK magnetic hanging strap, TL75 Test Leads, 2 x AA batteries, soft carrying case